# COLORADO CULTURAL RESOURCES INVENTORY

## **Greeley 8th Avenue Survey**

## **Historical and Architectural Reconnaissance Form**

## **IDENTIFICATION**

1. Current Property Name: Connections for Independent Living

Historic Property Name Wheeler Realty Co., Flood & Peterson Co.

Resource Classification: Building
 Ownership: Private

Owner(s) contact info:

# Eligibility Evaluation (OAHP use only) Date \_\_\_\_\_\_ Initials \_\_\_\_\_

\_\_\_\_ Determined Eligible – NR

OAHP Site #: 5.WL.7841

\_\_\_ Determined Eligible - SR Needs Data

\_\_\_\_ Eligible District – Contributing

\_\_\_\_ Eligible District - Noncontributing

## **LOCATION**

Street Address: 1331 8th Avenue
 Municipality: Greeley, Colorado

6. County: Weld

7. USGS Quad (7.5'): Greeley, Colorado year: 1950 Photorevised 1980

8. Parcel Number: **096108215008** 

9. Parcel Information: Lot(s): 4 Block: 104 Addition: Greeley Original Townsite

10. Acreage: < 1 (5328 square feet)

11. PLSS information: Principal Meridian: 6th Township: 5 North Range: 65 West

SW1/4 SW1/4 NE1/4 NW1/4 of section 8

12. Location Coordinates: Zone 13 526197 mE 4474119 mN

## DESCRIPTION

13. Construction features (forms, materials)

Property Type: One Story Commercial Building

Building Plan: Rectangular Plan

Dimensions in Feet: 52' N-S by 96' E-W, plus a 12' N-S by 28' E-W lower one story attached garage

extension at the south end of the west (rear) elevation

Stories: One

Architectural Style/Type: Modern Movements

Foundation: Concrete

Walls: Painted cream yellow color stucco, with painted red stuccoed corners and accent

lines.

OAHP Site #: 5.WL.7841

	Windows:	corner of the b	Bands of floor-to-ceiling fixed-pane windows wrap around the front northeast corner of the building. Four vertically-oriented windows are evenly spaced along the rear section of the north elevation. The west (rear) elevation contains three vertically-oriented fixed-pane windows.						
	Roof: The roof is flat, with flat parapets extending above the roof line at the befront northeast corner where this corner of the building is recessed und corner of the roof.								
	Chimney(s):	N/A	VA						
	Porch(s) / Doors:	entry into the l metal-frame do sidewalk along	A glass-in-metal-frame door, with a sidelight and a transom light, is the primar entry into the building at the east end of the north elevation. Another glass-in-metal-frame door (not currently in use) enters the east elevation from the front sidewalk along 8 <sup>th</sup> Avenue. Another glass-in-metal-frame door enters the west (rear) elevation.						
	Additions:	N-S by 28' E-W are clad with p yellow, side-hi	A lower flat-roofed addition to the south end of the west elevation measures 12' N-S by 28' E-W. The addition rests on a concrete foundation, and its exterior walls are clad with painted cream yellow color stucco. A set of paired painted cream yellow, side-hinged, vertical wood plank doors are located on the west elevation. A set of paired painted cream yellow color metal doors are located on the north elevation.						
14.	Landscape (important features of the immediate environment)								
	☐ Garden ☐	Mature Plantings	re Plantings		■ Parking Lot				
	☐ Driveway ■	Sidewalk	☐ Fence	☐ Seating					
HIST	ORICAL ASSOCIA	TIONS							
15. 16. 17.	Historic function/use: Current function/use: Date of Construction: Other Significant Date	Religion / Rel 1958 (actual)	rade / Business/Professional (real estate and insurance offices) ligious Facility (per city directories, Sanborn maps, and Assessor records)						
18.	Associated NR Areas of Significance								
	☐ Agriculture	Architecture	☐ Archaeology	☐ Art	■ Commerce				
	☐ Community Planning & Development	☐ Conservation	☐ Economics	☐ Education	☐ Engineering				
	☐ Entertainment/Rec.	☐ Ethnic Heritage	e ☐ Exploration/ Settlement	☐ Health/Medicine	☐ Industry				
	☐ Invention	☐ Landscape Architecture	□ Law	☐ Literature	☐ Maritime History				
	☐ Military	☐ Performing Art	s 🗆 Philosophy	☐ Politics/Gov't.	☐ Religion				
	☐ Science	☐ Social History	☐ Transportation	☐ Other					
19.	Associated Historic Context(s) (if known): City of Greeley 8th Avenue Survey; Greeley Downtown Historic District								
20.	Retains Integrity of:								

OAHP Site #: 5.WL.7841

#### 21. Notes:

This building is located on the west side of the 1300 block of 8<sup>th</sup> Avenue. The façade fronts directly onto a wide concrete sidewalk with brick pavers along the curb line. Asphalt parking lots are adjacent to the building's north and south sides, and behind the building to the west. The historic Meeker House property at 1324 9<sup>th</sup> Avenue is directly west of this property. The building's exterior has been significantly altered in recent decades so that it has lost much of its historic physical integrity.

#### 22. Sources:

The Greeley City and Rural Route Directory. (Generally published annually by the Greeley Tribune-Republican Publishing Company.)

Sanborn Insurance Company maps for Greeley, Colorado dated June 1886, December 1887, January 1891, October 1895, January 1901, January 1906, October 1909, January 1918, April 1927, September 1946 (as an update of the April 1927 Sanborn maps), August 1968 (also as an update of the April 1927 Sanborn maps).

Weld County Assessor Property Information Map. http://www.co.weld.co.us/maps/propertyinformation

Weld County Assessor Property reports. <a href="https://propertyreport.co.weld.co.us">https://propertyreport.co.weld.co.us</a>

## FIELD ELIGIBILITY RECOMMENDATIONS

Local Landmark Eligible?	□ yes	■ no	□ needs data	
Individually State Register Eligible?	□ yes	■ no	□ needs data	
Individually National Register Eligible?	□ yes	■ no	□ needs data	
Contributes to a Potential Historic District?	□ yes	□ no	□ needs data	■ property is not located within a potential district

### RECORDING INFORMATION

Recorded by: Carl McWilliams Date: September 30, 2015

Affiliation/Organization: Cultural Resource Historians LLC Phone Number: (970) 493-5270


Report title: Greeley 8th Avenue Comprehensive

**Historic Resource Survey** 

Project Sponsor: City of Greeley Historic Preservation Office


Photo Log: CD 1, Images 73-77

# SKETCH PLAN



## **LOCATION MAP**

# 1331 8th Avenue






CD 1, Image 73, View to NW of south side and façade (east)



CD 1, Image 74, View to west of façade (east)





CD 1, Image 75, View to south of north side



CD 1, Image 76, View to SE of north side and rear (west)

OAHP Site #: 5.WL.7841



CD 1, Image 77, View to East of rear (west)