COLORADO CULTURAL RESOURCES INVENTORY

Greeley 8th Avenue Survey

Historical and Architectural Reconnaissance Form

IDENTIFICATION

Current Property Name: Randy Premer Auto Repair
 Historic Property Name Ray & Gus Independent Ga

Resource Classification:

Ray & Gus Independent Gas, Seery's Service Station Building Private

Ownership: P
 Owner(s) contact info:

OAHP Site #: 5.WL.7865

Eligibility Evaluation (OAHP use only	()
Date Initials	
Determined Eligible – NR	
Determined Eligible - SR Needs Data	
Eligible District – Contributing	
Eligible District - Noncontributin	a

LOCATION

2.

4.	Street Address:	1300 8th Avenue		
5.	Municipality:	Greeley, Colorado		
6.	County:	Weld		
7.	USGS Quad (7.5'):	Greeley, Colorado	year: 1950	Photorevised 1980
8.	Parcel Number:	096108214001		
9.	Parcel Information:	Lot(s): 4	Block: 103	Addition: Greeley Original Townsite
10.	Acreage:	< 1 (7125 square feet)		
11.	PLSS information:	Principal Meridian: 6th	Township: 5 North	Range: 65 West
	SE¼ SW¼ NE¼ NW¼	of section 8		
12.	Location Coordinates: Datum: NAD83	Zone 13	526261 mE	4474187 mN

DESCRIPTION

13. Construction features (forms, materials)

Property Type:	One Story Commercial Building
Building Plan:	Rectangular Plan
Dimensions in Feet	2250 square feet
Stories:	One
Architectural Style/Type:	Modern Movements / Oblong Box Gas Station
Foundation:	Concrete
Walls:	The west-facing (façade) wall and the north-facing wall are made of brown brick laid in running bond, accented with a wide band of red brick at the bottom and a narrow stringcourse of red brick at a level above the door and window openings.

	OAHP Site #: 5.WL.7865
	The north end of the east-facing (rear) wall is made of brown brick, but without the red brick accents. The remainder of the east-facing wall and the south-facing wall are made of grey brick laid in common bond.
Windows:	Single-light display windows in silver metal frames flank the entry into the customer service office at the north end of the façade. A 2-light display window is located just around the corner at the west end of the north-facing wall. The south-facing wall contains two small 3-light hopper industrial sash windows with brown brick rowlock sills.
Roof:	The roof is flat, decorated along the west and north sides, with an applied faux roof eave clad with brown asphalt composition shingles. Advertising signs for "UNIROYAL" and "MICHELIN" are attached to the east-facing (façade) eave.
Chimney(s):	N/A
Porch(s) / Doors:	A glass-in-silver-metal-frame door enters into the customer service office from within a slightly recessed entryway near the north end of the façade. The southern portion of the façade contains four painted beige color wood-paneled rollaway garage service bay doors. These garage bay doors are separated by brown brick columns with red brick accents. The east end of the north-facing wall contains two doors which enter into restrooms, respectively labeled "LADIES" and "MEN." Both of these doors are painted cream yellow, wood-paneled, with frosted glass upper sash lights and with frosted glass transom lights.

14. Landscape (important features of the immediate environment)

Garden	□ Mature Plantings	Designed Landscape	□ Walls	Parking Lot
Driveway	Sidewalk	Fence	□ Seating	

HISTORICAL ASSOCIATIONS

15.	Historic function/use:	Commerce/Trade / Gas Station
	Current function/use:	Commerce/Trade / Specialty Store (automobile repair facility)
16.	Date of Construction:	Circa 1954 (per city directories, Sanborn maps, and Assessor records)
17.	Other Significant Dates:	N/A

18. Associated NR Areas of Significance

■ Location □ Setting

	□ Agriculture	Architecture	□ Archaeology	□ Art	Commerce
	Community Planning & Development	□ Conservation	□ Economics	□ Education	
	☐ Entertainment/Rec.	Ethnic Heritage	Exploration/ Settlement	□ Health/Medicine	□ Industry
	□ Invention	Landscape Architecture	□ Law	Literature	□ Maritime History
	□ Military	Performing Arts	Philosophy	Politics/Gov't.	□ Religion
	□ Science	□ Social History	Transportation	□ Other	
19.	 Associated Historic Context(s) (if known): 		City of Greeley 8th Ave District	enue Survey; Greeley D	owntown Historic

Design

Workmanship

Materials

Feeling

Association

20. Retains Integrity of: 21. Notes:

This building is located at the southeast corner of 8th Avenue and 13th Street. It was built circa 1954, replacing the Swedish Evangelical Lutheran Immanuel Church which had occupied the site since circa 1908. Asphalt and concrete parking lots / driveways surround the building, except near the rear northeast corner where there is a small area of planted grass.

22. Sources:

The Greeley City and Rural Route Directory. (Generally published annually by *the Greeley Tribune-Republican* Publishing Company.)

Sanborn Insurance Company maps for Greeley, Colorado dated June 1886, December 1887, January 1891, October 1895, January 1901, January 1906, October 1909, January 1918, April 1927, September 1946 (as an update of the April 1927 Sanborn maps), August 1968 (also as an update of the April 1927 Sanborn maps).

Weld County Assessor Property Information Map. http://www.co.weld.co.us/maps/propertyinformation


Weld County Assessor Property reports. https://propertyreport.co.weld.co.us

FIELD ELIGIBILITY RECOMMENDATIONS

Local Landmark Eligible?	■ yes	□ no	□ needs data	
Individually State Register Eligible?	□ yes	🗆 no	■ needs data	
Individually National Register Eligible?	□ yes	🗆 no	needs data	
Contributes to a Potential Historic District?	□ yes	🗆 no	□ needs data	property is not located within a potential district

RECORDING INFORMATION

Recorded by:	Carl McWilliams	Date: November 30, 2015
Affiliation/Organization:	Cultural Resource Historians LLC	Phone Number: (970) 493-5270
Report title:	Greeley 8 th Avenue Comprehensive	
	Historic Resource Survey	
Project Sponsor:	City of Greeley Historic Preservation Office	
Photo Log:	CD 1, Images 216	
	CD 2, Images 1-3	




SKETCH PLAN

LOCATION MAP

1300 8th Avenue







CD 2, Image 1, View to NE of façade (west) and south side



CD 1, Image 2, View to SE of façade (west)



CD 2, Image 3, View to SW of north side and rear (east)